














New Modulamm four-leg chair




New Modulamm four-leg chair




New Modulamm seat on beam


• 25 • 51 • 51 •




• 53 •
• 29 •




• 29 • 55 • 55 •




• 53 •
• 40 •



• 34 • 60 • 60 •




• 53 •




New Modulamm seat on beam


85 29




85 40









85 59



85 53
29



New Modulamm seat on beam - feet with registers



New Modulamm seat on beam - feet with registers

